

BELVEDERE CLUB 2019 ARCHITECTURAL INVENTORY



Site: 29

Historic Name N/A

Year Built c. 1890

Architectural Style Folk Victorian

The two-and-half story cottage has clapboard siding with shingle siding in the gable fronts. The matching gable fronts connected by a side gable massing is indicative of the Folk Victorian style. The cottage has received a new foundation and the roof has been raised to create a taller attic. The shed roof dormer in the center of the front roof is new, as is the south side gable and addition. The arched vents in the gable fronts are new.

Significant Features

- Full width front porch with Doric columns. It is unknown if the current configuration is original.

Condition

The cottage is in good repair no issues are apparent.

ADDITIONAL PHOTOS

Unknown date, pre-2007



2019 – East



West and north



West

