

BELVEDERE CLUB 2019 ARCHITECTURAL INVENTORY



Site: 209

Historic Name N/A

Year Built c. 1900

Architectural Style Shingle

This one-and-a-half story cottage has narrow vertical siding at the first floor and shingles at the second. Without historic photos it is difficult to tell whether the shingled pillars supporting the large gable front creating a deep second floor porch is original. The large brick chimney on the south wall has been removed to the first floor and roofed over.

Significant Features

- Gable front roof with shed roof dormers along both sides.
- Full width porch with railing, square pillars at corners and tall shingled pillars in the center supporting the projecting gable front roof with arches.
- Deep second floor porch with shingle sided knee wall in front.
- Narrow vertical siding at first floor and shingles at second floor.
- Diamond pane and multi-pane windows.
- Two outbuildings at rear of property.

Condition

The cottage appears to be in good repair with no apparent issues although the large shrubbery that touches the sides could cause moisture damage in the future. Moss is growing on portions of the roof.

ADDITIONAL PHOTOS

2007



2019 – East and north



North and west



West



Outbuildings

